

Date 110607? Campaign TEST FLIGHTS Flight JF1 From Dry Run in Hangar To

i.e. Dry Run in hangar w/ Jonathan

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.06

I. Preflight

A. Day(s) before flight Date = 110607

1) Prepare trap with clean glass beads filled to 1 inch from bottom

2) Install trap in dewar Trap Letters Top/Bottom = B / D

3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures

PaWT 850 PaSP 800 PLi840 19 TMan 24.5 UTC = 20:44

4) Crack and close green valves, then record cylinder pressures

LS 1830 HS 2030 LP 1590 UTC = 21:30

~~1960~~ ~~LT 2460~~ WT 1720 CylT 22.49

5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights) ~~to station AO2 windows~~

6) Stop program, close Visual Basic, and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off Instrument Operator JOB

1) Rack power switch on

2) O₂ box Power breaker on

3) Laptop power on

4) Pump box Power breaker on

5) Load dry-ice in dewar to within 0.5 inches of lid UTC = :

6) Record hi-side cylinder pressures and changes overnight (P / Δ)

LS 1730 / 100 HS 2020 / 35 LP 1590 / 4

LT 1945 / 28 WT 1700 / 46 CylT2 402 / 4 (once inst. on)

7) Open green knobs four 1/4 turns and note any pressure changes (P / Δ)

LS 1840 / +110 HS 2050 / +30 LP ~1600 / 0

LT 1945 / 0 WT 1700 / 0

8) Close cylinder box lid

9) Vnc into into AO2 (192.168.84.138)

10) Start AO2 program by clicking play in higold.vdp

11) Ensure that no USB errors are present in boxes at bottom of screen

12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 19:06:50, Rack laptop time 19:06:47

13) Cylinder box Power breaker on

14) Record instrument pressures and changes overnight (P / Δ)

PaWT 851 / +1 PaSP 788 / -12 PLi840 223 / +13.3 TMan 24 / +5

15) Pump box Pump 2 breaker on

16) Manual VAC valve open

17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 88 torr (± 1). If not, adjust.

PaCO₂ 324 PaO₂ 87.0

18) Click Initialize Cal Flow button



Date 110607 Campaign HIPPO4 Flight JF01 From Dry Run in Hangar To

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 106 FISP (to bypass) 107
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 106 FISP (to cell) 106
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 19:16
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O2 signal = 9.26
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 1 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 790 SA Purge Flow 100 ← NOISY
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

noisy
↓

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>19:26</u>	<u>NA</u>	<u>0.64</u>	<u>1.2</u>	<u>NA</u>	<u>NA</u>	<u>13</u>	<u>NA</u>	<u>0.02</u>	<u>5.4</u>	<u>4.1</u>	<u>15.0</u>
<u>19:40</u>	<u>600</u>	<u>0.6</u>	<u>4.8</u>	<u>14.3</u>	<u>-5</u>	<u>3.8</u>	<u>18.7</u>	<u>0.02</u>	<u>4.6</u>	<u>4.3</u>	<u>16.5</u>
nominal	450	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 19:30
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Close WT 248 valve **EDIT:** "click close WT" to close WT248val

C. 20-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable)
- 3) Adjust / record program parameters (nominally set to a, 50, 2.5, 3, 4)
Flag a Cal Interval 50 Cal Period 2.5 Ltf 3 Wtf 4
- 4) Click Start button on main screen UTC = 19:46:
- 5) Note cryo temperature Cryo =
- 6) Immediately before runway, switch 3-way valve to inlet UTC = : :
- 7) Note time of wheels up UTC = : :
- 8) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

Date 110607 Campaign HIPPO4 Flight JFO1 From Dry Run To h Henger

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cal.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = __ : __ : __
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = __ : __ : __
- 3) On final descent, open Line Purge cylinder green valve and on/off valve

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cal at same altitude on the way up and down above 29 kft, and avoiding any cal on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = __ : __ : __
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature Cryo = _____
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves** EDIT: ALL 5 includes Line Purge
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Date 110607 Campaign HIPPO4 Flight TFO1 From BTC To BTC *(via FMN)*

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.06

I. Preflight

A. Day(s) before flight

Date = 110606

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT PaSP PLi840 TMan UTC = :
- 4) Crack and close green valves, then record cylinder pressures
LS 1900 HS 2100 LP 1690 UTC = 20 : 30
LT 2000 WT 1900 CylT2
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off

Instrument Operator BBS

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 14 : 00
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
~~LS 1780 / -110 HS 2050 / -50 LP 1700 / +10~~
LT 1980 / -10 WT 1870 / -30 CylT2 26.8 / (once inst. on)
- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1900 / +120 HS 2100 / +50 LP 1700 /
LT 1980 / WT 1880 / +10
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 2 : 27:28 , Rack laptop time 2 : 27:30
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 838 / PaSP 802 / PLi840 20.08 / TMan 26 /
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 88 torr (± 1). If not, adjust.
PaCO₂ 326 PaO₂ 87
- 18) Click Initialize Cal Flow button

*Leak → fix
found bubbles on
LS 1/8" → tightened
two 1/8" fittings on both
LS + HTS*

Date 110604 Campaign HIPPO4 Flight TF01 From BSC To BSC
ENTT?

- 19) Ensure that flow starts through both lines (110 ± 10)
 FIWT (to cell) 110 FISP (to bypass) 110
- 20) Toggle changeover to check flows in other position
 FIWT (to bypass) 110 FISP (to cell) 110
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 14:57
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 8.79
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
 PaSA 791 SA Purge Flow 100
- 34) Snoop trap fittings
- 35) >= 10 min. after lamp on record values in first row of table below

110613
EOT
 change ppgt in
 code to 110

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>15:02</u>	NA	0.8	3.5	NA	NA	11	NA	0.03	5.3	4.7	3.6
<u>15:40</u>	<u>609</u>	0.8	1.9	10	-6	↓	16	0.02	4.8	4.6	4.0
nominal	<u>450</u>	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

EOT

- 36) Enable changeover valve (uncheck disable) UTC = 15:07
- 37) >= 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Close WT 248 valve

EOT

C. 20-min before, take-off

120

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable)
- 3) Adjust / record program parameters (nominally set to a, 50, 2.5, 3, 4)
 Flag 9 Cal Interval 20 Cal Period 2.5 LTF 3 WTF 4
- 4) Click Start button on main screen UTC = 15:42:55
- 5) Note cryo temperature Cryo = -80
- 6) Immediately before runway, switch 3-way valve to inlet UTC = 17:03:17
- 7) Note time of wheels up UTC = 17:04:08
- 8) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

all change to 30
 during flight

edited A02ads
 to -50 to
 get LP on
 scale

change in
 code

@ 16:51 just after UTC set to LS for taxi
 and take-off (also looking @ LS rollover)
 16:02:30 oshac rebooting data system
 16:59:06-12 taxi start
 17:07:22 → AUTO
 17:08:30
 bump

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 17:27:40
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 18:22:05
- 3) On final descent, open Line Purge cylinder green valve and on/off valve

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

17:57:00 low over FMN, 18111 (had tried to abort cal, but acc. forced) want to MAX

III. Postflight

- 1) Note time of wheels down 18:23:50, back to Auto UTC = 18:56:48
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature Cryo = 80.4
- 4) Click Stop button *allow any cals in prog to finish*
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

18:140 - big humps
18:52:30 forcing cal to humps on landing
(1665 @ 55:40 ~)

BBS

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.06

I. Preflight

A. Day(s) before flight Date = 20110608

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT ___ PaSP ___ PLi840 ___ TMan ___ UTC = ___ : ___
- 4) Crack and close green valves, then record cylinder pressures
LS ___ HS ___ LP ___ UTC = ___ : ___
LT ___ WT ___ CylT2 ___
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off Instrument Operator JDB (+BS)

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 14:15
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1770 / ___ HS 2010 / ___ LP 1600 / ___
LT 1450 / ___ WT 1690 / ___ CylT2 251 / ___ (once inst. on)
- 7) Open green knobs four 1/4 turns and note any pressure changes (P / Δ)
LS 1855 / +85 HS 2055 / +45 LP 1570 / -30 (very rough - hard to see)
LT 1460 / +10 WT 1695 / +5
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 14:33:11, Rack laptop time 14:33:14
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 831 / ___ PaSP 766 / ___ PLi840 232 / ___ TMan 197 / ___
- 15) Pump box Pump 2-breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 88 torr (± 1). If not, adjust.
PaCO₂ 325 PaO₂ 89
- 18) Click Initialize Cal Flow button

EO2T

Date 20110609 Campaign HP004 Flight TF02 From B02 To B02

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 101 FISP (to bypass) 105
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 103 FISP (to cell) 103
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 14:29
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 8.7
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 1 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 790 SA Purge Flow 104 → much better than yesterday
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
14:51	NA	0.77	1.0	NA	NA	9	NA	0.03	4.6	4.1	3.3
15:03	534	0.67	1.4	19	-7.9	4.8	27	0.03	4.7	4.3	3
nominal	450	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 14:53
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Close WT 248 valve **EDIT**: Click "Close WT" to close WT 248

C. 20-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) ²⁰
- 3) Adjust / record program parameters (nominally set to a, 50, 2.5, 3, 4)
Flag ~~20~~ Cal Interval 20 Cal Period 2.5 LTF 3 WtF 4
- 4) Click Start button on main screen UTC = 15:28:26
- 5) Note cryo temperature Cryo = -81
- 6) Immediately before runway, switch 3-way valve to inlet UTC = 16:36:30
- 7) Note time of wheels up UTC = 16:36:50
- 8) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

17:13 - closed Inlet on/off valve
forget to @ takeoff

✓ reset cal int to 45 from 20

16:42 changed to 45 min cal int

EDIT
get 2 cells in before flight...
set cal int to 45 initially and start. 25 min before flight...
15:45-16:00
15:45-16:00

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 17:15:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings *conducted early* UTC (start) = 20:38:00
- 3) On final descent, open Line Purge cylinder green valve and on/off valve 22:35:00 ~

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 22:40:10
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 22:41:13
- 3) Note cryo temperature Cryo = -80.0
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Simon
Anne
David

To Do:

- Add some sort of air for reading
LinePurge ~~with~~ Dial-mirror? strip on side
- Turn AO₂ cylinder in MED rack around
check whether this will fit - mounting
rack may need to be remade.
- Load old checksheet scan onto AO₂ laptop
→ on pen drive ⇒ laptop
- Add edits to AO₂ check to extend check
log time for whole flight and to
record
- Grab kitchen timer for AO₂ rack
for sample time reminders
- Flush filters 4, 17 w/ low CO₂ air.

MED breathes 17:24:45 ⇒ 17:26:30

- ~~Bypass P creeps up/down to equil w/ something
seems to want to go to ~840, so looks
like it's leaving to sample P, prob on
upstream side to meter PSA~~
- MED-PSA and MED-byp. signals coming
out of rack to Aeros are reversed
- Talk to Greg about reversing these
- check if Trap 2 outlet is at all iced

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

- A. Day(s) before flight Date = 110613
- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
 - 2) Install trap in dewar Trap Letters Top/Bottom = AO
 - 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 837 PaSP 807 PLi840 28 TMan 29 UTC = 22:13
 - 4) Crack and close green valves, then record cylinder pressures
LS 1810 HS 2030 LP 1570 UTC = 22:18
LT 1960 WT 1480 CylT2 25
 - 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
 - 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

- B. 2-hours before take-off Instrument Operator JDB
- 1) Rack power switch on
 - 2) O₂ box Power breaker on
 - 3) Laptop power on
 - 4) Pump box Power breaker on
 - 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 14:13
 - 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1730/-50 HS 1980/-50 LP 1580/+10
LT 1960/0 WT 1490/-10 CylT2 266/-24 (once inst. on)
 - 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1855/+125 HS 2050/+80 LP 1590/+10
LT 1960/0 WT 1495/+5
 - 8) Close cylinder box lid
 - 9) Vnc into into AO2 (192.168.84.138)
 - 10) Start AO2 program by clicking play in higold.vdp
 - 11) Ensure that no USB errors are present in boxes at bottom of screen
 - 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 14:23:33, Rack laptop time 14:23:34
 - 13) Cylinder box Power breaker on
 - 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 831/-6 PaSP 800/-7 PLi840 29.6/-1.6 TMan 27.9/-1.1
 - 15) Pump box Pump 2 breaker on
 - 16) Manual VAC valve open
 - 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 88 torr (± 1). If not, adjust.
PaCO₂ 325 PaO₂ 92.8
 - 18) Click Initialize Cal Flow button

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 110 FISP (to bypass) 110
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 110 FISP (to cell) 110
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ± 2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 \pm 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (± 0.1), PdSP (± 0.1), and PdO2 (± 0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 14:36
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.2
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 1 psig
- 33) Ensure that PaSA stabilizes near 795 (± 10) torr after 2 min.
PaSA 791 SA Purge Flow 106.
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>14:46</u>	NA	<u>0.7</u>	<u>2</u>	NA	NA	<u>135</u>	NA	<u>0.03</u>	<u>5</u>	<u>4.7</u>	<u>3.7</u>
<u>15:00</u>	<u>563</u>	<u>0.6</u>	<u>2.6</u>	<u>18</u>	<u>-15</u>	<u>1.2</u>	<u>33</u>	<u>0.02</u>	<u>5.3</u>	<u>5.1</u>	<u>3.2</u>
nominal	450	0.7	2.0	± 10	± 10	± 10	± 20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 14:26
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve

C. 40-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable)
- 3) Adjust / record program parameters (initially set to a, 15, 2.5, 3, 2)
Flag a Cal Interval 15 Cal Period 2.5 LTF 3 Wtf 2
- 4) Click Start button on main screen UTC = 15:36:40
- 5) Note cryo temperature Cryo = -81
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4 \rightarrow 16:07:05
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 16:02:30
- 8) Note time of wheels up UTC = 16:03:42
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

Date 110614 Campaign H4 Flight RF01

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings 110614 - AO2 breathst 1 UTC (start) = 16:45:00 - 16:46:15
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 20:35:00 → 20:36:00
- 3) On final descent, open Line Purge cylinder green valve and on/off valve 21:28:00

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 21:53:35
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature Cryo = -78
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

To do in ANCHORAGE:

- As much as possible, write code to run post-flight to analyze flows, etc.
- Finish introduction
- ✓ Correct all AO_2 checksheets to reflect '45 mins before takeoff and Calper \rightarrow 3.0 instead of 2.5
- Test IRS low inlet PSetpoint
- Fix ~~LD~~ leak?
- ✓ Upload data
- Upload checksheet scans.
- Sort out access to Wiki
- Change prepurge in Rabbit to 50 seconds.

Date 110616 Campaign U1PPO4 Flight RFO2 From PANC To PANC

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

Used one from plastic bag prepared in R/F, checked: dry w/ heads

A. Day(s) before flight

Date = 110615

- ✓1) Prepare trap with clean glass beads filled to 1 inch from bottom
- ✓2) Install trap in dewar Trap Letters Top/Bottom = A / C
- ✓3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures

PaWT 989 PaSP 967 PLi840 26 TMan 21 UTC = 17:42

Note @ 19:30 on 110615 hi/low
LS-1740/3.4
HS-1950/3.8
LT-1890/2.7
WT-1270/4.35

- ✓4) Crack and close green valves, then record cylinder pressures
LS 1750 HS 1940 LP 1520 UTC = 17:46
LT 1880 WT 1270 CylT2 24.99

- ✓5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)

- ✓6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off

Instrument Operator _____

- ✓1) Rack power switch on
- ✓2) O₂ box Power breaker on
- ✓3) Laptop power on ← cyl box power on (in order to get
- ✓4) Pump box Power breaker on
- ✓5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 16:06
- ✓6) Record hi-side cylinder pressures and changes overnight (P / Δ)

LS 1715/-35 HS 1900/-40 LP 1500/-20
LT 1890/+10 WT 1290/+20 CylT2 18.47/-6.5 (once inst. on)

- ✓7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1760/+45 HS 1970/+70 LP 1500/0
LT 1900/+10 WT 1290/0

- ✓8) Close cylinder box lid
- ✓9) Vnc into into AO2 (192.168.84.138)
- ✓10) Start AO2 program by clicking play in higold.vdp
- ✓11) Ensure that no USB errors are present in boxes at bottom of screen
- ✓12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 16:24:58, Rack laptop time 16:25:00

- ✓13) Cylinder box Power breaker on
- ✓14) Record instrument pressures and changes overnight (P / Δ)
PaWT 967-23 PaSP 956/-11 PLi840 31/+5 TMan 18/-3

- ✓15) Pump box Pump 2 breaker on
- ✓16) Manual VAC valve open
- ✓17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 319 PaO₂ 93
- ✓18) Click Initialize Cal Flow button

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 96 FISP (to bypass) 94
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 96 FISP (to cell) 93
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 16:38
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.5
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on 1
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA ⁷⁸⁵/₇₉₂ SA Purge Flow 168
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
16:51	NA	846	1.0	NA	NA	8.2	NA	0.028	6.0	4.5	4.15
17:13	<u>492</u>	<u>75</u>	<u>1.9</u>	<u>28</u>	<u>-13</u>	0.6	<u>26</u>	0.022	6.2	4.4	4.7
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

Circled values taken @ 17:25 because not recorded earlier that was just skipped 39, 40 and went to C.3

- 36) Enable changeover valve (uncheck disable) UTC = 16:57
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve
- C. 45 -min before take-off
- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) 3.0
- 3) Adjust / record program parameters (initially set to a, 15, ~~25~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 Ltf 3 Wtf 2
- 4) Click Start button on main screen UTC = 17:21:16
- 5) Note cryo temperature Cryo = -78
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 18:08:15
- 8) Note time of wheels up UTC = 18:09:20
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings
- 3) On final descent, open Line Purge cylinder green valve and on/off valve

UTC (start) = 19:28:20

UTC (start) = 02:18:10

-02:18:50

19:29:30
BUT BADLY
CHOSEN
TRANSITIC
ZONE ~
TROBPAU

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

save PNG

III. Postflight

- 1) Note time of wheels down
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

UTC = 03:04:20

Cryo = -78.6

forget

couldn't

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight Date = 20110617

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 846 PaSP 837 PLi840 21 TMan 23.6 UTC = 18:18
- 4) Crack and close green valves, then record cylinder pressures
LS 1710 HS 1900 LP 1490 UTC = 18:23
LT 1860 WT 1000 CylT2 16.3
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

was (in log)
1750 1900
1830 1240

B. 2-hours before take-off Instrument Operator JDB

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 16:05
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1720 / +10 HS 1880 / +20 LP 1420 / -70
LT 1890 / +30 WT 980 / +20 CylT2 19.5 / -4 (once inst. on)
- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1720 / +10 HS 1910 / +30 LP 1460 / +10
LT 1890 / +0 WT 990 / +10
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 16:28:01, Rack laptop time 16:28:02
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 832 / -14 PaSP 814 / -23 PLi840 4.7 / +3.7 TMan 18 / -5.6
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 320 PaO₂ 93 (BS says this is fine)
- 18) Click Initialize Cal Flow button

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 98 FISP (to bypass) 97
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 97 FISP (to cell) 95
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ± 2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (± 0.1), PdSP (± 0.1), and PdO2 (± 0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 16:36
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.1
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (± 10) torr after 2 min.
PaSA 790 SA Purge Flow 110
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

↓
17:23 ≈ 9.7

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSan
<u>16:49</u>	NA	<u>0.78</u>	<u>1.0</u>	NA	NA		NA				
<u>17:23</u>	<u>563</u>	<u>0.8</u>	<u>4</u>	<u>14</u>	<u>-9</u>	<u>0.4</u>	<u>26</u>	<u>0.03</u>	<u>6.65</u>	<u>5.31</u>	<u>6.3</u>
nominal	500+	0.7	2.0	± 10	± 10	± 10	± 20	0.05	5.0	5.0	5.0

*brought
PaCO₂ up
to 355 to
get flow up
to 110,
tried moving
HA-3, but
it didn't
seem to
achieve
anything*

- 36) Enable changeover valve (uncheck disable) UTC = 17:06
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve

C. 40-min before take-off

45

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable)
- 3) Adjust / record program parameters (initially set to a, 15, 3.0, 3, 2)
Flag 3.0 Cal Interval 15 Cal Period 3.0 LTF 3 WtF 2
UTC = 17:25:25
Cryo = -78.8
- 4) Click Start button on main screen
- 5) Note cryo temperature
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WtF to 4 → 18:03:05
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 17:59:50
- 8) Note time of wheels up UTC = 18:01:06
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

18:03:40

Keep looking

Date 110618 Campaign HIPPO4 Flight RF03

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cal.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 110618-AO2-breath test
-33-34. P1g
- 1) At high point of first ascent, while sampling air, conduct 30-second breath test
on inlet fittings UTC (start) = 18:33:00 - 18:34:00
 - 2) At high point of last ascent, while sampling air, conduct 30-second breath test
on inlet fittings UTC (start) = 01:39:00 -
 - 3) On final descent, open Line Purge cylinder green valve and on/off valve 02:29:50

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cal at same altitude on the way up and down above 29 kft, and avoiding any cal on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 02:37:25
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 023810
- 3) Note cryo temperature Cryo = -77.2
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Date 110622 Campaign HIPPO4

~~Journal Flight Log~~
Flight ~~RAIR~~ From PANC To RAIR
RPO4

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight

Date = 110620

*Cyl USB Error on
Cyl box originally
prob. because USB
of CB was knocked
during post-flight
and readjusted/connected
and no more
USB error*

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = A / C
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 846 PaSP 837 PLi840 30.8 TMan 21.9 UTC = 21:45
- 4) Crack and close green valves, then record cylinder pressures
LS 1710 HS 1900 LP 1410 UTC = 21:48
LT 1900 WT 775 CylT2 ()
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off

Instrument Operator JJB

VDD

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 21:15
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1760 / +50 HS 1835 / -65 LP 1390 / +20
LT 1930 / +30 WT 690 / -15 CylT2 21.4 / () (once inst. on)
- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1750 / -10 HS 1930 / +95 LP 1430 / +40
LT 1930 / +10 WT 770 / +80
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 21:34:57, Rack laptop time 21:34:59
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 867 / +18 PaSP 846 / +9 PLi840 21.5 / -9.3 TMan 26.8 / +4.9
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 329 PaO₂ 86.5 (acceptably low from conversion before RPO3)
- 18) Click Initialize Cal Flow button

D

Date 110622

Campaign MIPPO4

Flight ~~RFO4~~
RFO4

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 113 FISP (to bypass) 106
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 114 FISP (to cell) 104
- ? 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ± 2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 ± 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (± 0.1), PdSP (± 0.1), and PdO2 (± 0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 4:47
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 8.02
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (± 10) torr after 2 min.
PaSA 790 SA Purge Flow 109
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>21:57</u>	NA	<u>0.7</u>	<u>1.1</u>	NA	NA	<u>9.2</u>	NA	<u>0.07</u>	<u>4.8</u>	<u>4.5</u>	<u>4.6</u>
<u>22:08</u>	<u>579</u>	<u>0.68</u>	<u>3.5</u>	<u>18</u>	<u>-9.6</u>	<u>1.4</u>	<u>21.4</u>	<u>0.02</u>	<u>4.9</u>	<u>5.6</u>	<u>4.8</u>
nominal	500+	0.7	2.0	± 10	± 10	± 10	± 20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 21:58
- 37) ≥ 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve
- C. 45-min before take-off

Now
50 mins
before
take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) ^{3.0}
- 3) Adjust / record program parameters (initially set to a, 15, ~~21.5~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 Ltf 3 Wtf 2
- 4) Click Start button on main screen UTC = 22:10:46
- 5) Note cryo temperature Cryo = -79.8
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 23:15:38
- 8) Note time of wheels up UTC = 23:16:13
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

SP2 issue
caused 10 min
delay.
Forced on 2
10 test, and
set back to 50

EDIT

add time

@ 13:20:00

Date 110622

Campaign HI PPO4

Flight ~~RF04~~

RF04

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 23:42:00 - 43:00

2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = : :

3) On final descent, open Line Purge cylinder green valve and on/off valve

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

1) Note time of wheels down UTC = 07:36:15

2) As soon as off runway, request permission and switch inlet 3-way to line purge

3) Note cryo temperature Cryo = -78.1

4) Click Stop button

5) Close manual VAC valve

6) **Close all 4 cal cylinder green valves**

7) Close cylinder box lid

8) Wait 5 to 10 minutes after touchdown

9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve

10) Cylinder box Power breaker off

11) Pump box Pump 2 breaker off

12) Pump box Pump 1 breaker off

13) Pump box Power breaker off

14) Close program and Visual Basic

15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive

16) Shut down AO2 PC

17) Shut down laptop

18) After green "SP to Cell" light has gone out, O₂ box Power breaker off

19) Rack power switch off

20) Pull trap, jumper quick-connects, and install stopper

21) Open trap and remove glass beads

22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)

23) email a scan of this checksheet to BBS (or fax if scanner not available)

Didn't
measure

To Do 06/23

- Set up run (by changing A02 comp time \rightarrow 23:59.)
that runs LP over midnight.

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight Date = 110623

- ✓ 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- ✓ 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- ✓ 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 867 PaSP 848 PLi840 25 TMan 23 UTC = 21:37
HS JUMPS UP
- ✓ 4) Crack and close green valves, then record cylinder pressures
LS 1660 HS 1860 LP 1370 UTC = 21:42
LT 1855 WT 530 CylT2 18.8
- ✓ 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- ✓ 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

Purging LP
from ~21:50
→

B. 2-hours before take-off Instrument Operator JDB

- ✓ 1) Rack power switch on
- ✓ 2) O₂ box Power breaker on
- ✓ 3) Laptop power on
- ✓ 4) Pump box Power breaker on
- ✓ 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 18:30
- ✓ 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1710 / +50 HS 1875 / +25 LP 1300 / -30
LT 1880 / +25 WT 470 / -60 CylT2 21.5 / +4.5 (once inst. on)
- ✓ 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1700 / -10 HS 1900 / +25 LP 1310 / +10
LT 1900 / +20 WT 470 / -0
- ✓ 8) Close cylinder box lid
- ✓ 9) Vnc into into AO2 (192.168.84.138)
- ✓ 10) Start AO2 program by clicking play in higold.vdp
- ✓ 11) Ensure that no USB errors are present in boxes at bottom of screen
- ✓ 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 06:42:08, Rack laptop time 06:42:08 (server had just come on)
(didn't - had to manually update)
- ✓ 13) Cylinder box Power breaker on
- ✓ 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 925 / +58 PaSP 825 / +23 PLi840 32 / +4.4 TMan 24 / +1
- ✓ 15) Pump box Pump 2 breaker on 29.4
- ✓ 16) Manual VAC valve open
- ✓ 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 327 PaO₂ 87
- ✓ 18) Click Initialize Cal Flow button

Date 110625 Campaign HIPPO4 Flight RFOS

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 108 FISP (to bypass) 100
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 107 FISP (to cell) 100
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 18:48
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.75
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 795 SA Purge Flow 107
- 34) Snoop trap fittings
- 35) >= 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>19:00</u>	<u>NA</u>	<u>0.75</u>	<u>0.88</u>	<u>NA</u>	<u>NA</u>	<u>7.6</u>	<u>NA</u>	<u>0.03</u>	<u>5.7</u>	<u>4.4</u>	<u>4.3</u>
<u>19:11</u>	<u>581</u>	<u>0.8</u>	<u>2.0</u>	<u>18</u>	<u>-15</u>	<u>1.2</u>	<u>33</u>	<u>0.03</u>	<u>5.3</u>	<u>5.3</u>	<u>4.0</u>
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 19:01
- 37) >= 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve

C. ⁴⁵~~40~~-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) 3.0
- 3) Adjust / record program parameters (initially set to a, 15, ~~20~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 LTF 5 WtF 2
- 4) Click Start button on main screen UTC = 20:08:00 (110623: 23:56:20)
- 5) Note cryo temperature Cryo = -78.6
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WtF to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 21:29:30
- 8) Note time of wheels up UTC = 21:30:10
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve
21:43:30

Date 110625 Campaign HIPPO4 Flight RF05

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 22:07:00 -08
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = : :
- 3) On final descent, open Line Purge cylinder green valve and on/off valve @ 04:03

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 04:18:13
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 041930
- 3) Note cryo temperature Cryo = -77.8
- 4) Click Stop button 04:33 - after 1st cal, as second was starting
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

A02 leak test

- o run all 4 refs in all way
- o then all the way back out
- o Note ~~Ps~~ on low side @ start, 15 mins later
Note PASA if possible.
- o Note Ps, PASA next morning

	LS	HS	LT	WT	PASA
04:37	12.6	11.9	11.2	13.5	877
04:55	12.7	11.0	11.0	13.4	785
05:25	12.7	10.95	11.0	13.4	784

Block knows all way out
after ~~Ps~~ spinning all way in
Green values then closed
Power off. Have 45 min. still so
powered up. PASA = 26 @ 5:10
PaSP = 785

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

(2 takeoff delays - so many additional notes were
I. Preflight and on 110628 RF06

A. Day(s) before flight Date = 110627

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = A / C
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record

pressures ← 110628

PaSA 27.1 ~~10.4~~ PaWT 3.5 PaSP -0.7 PLi840 12.0 TMan 23.8 UTC = 03:46 110628 8:4

- 4) Crack and close green valves, then record cylinder pressures HS/L5 1550/13.0 1740
LS 1580/12.9 HS 1780/11.4 LP 120/1.5 UTC = 01:47
LT 100/2.8 WT 1880/15.5 CylT2 10.3 1780/4.8 1840/11

- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off Instrument Operator JDB

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 20:30
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)

LS 1540/-10 HS 1720/-20 LP 1180/-20 recorded @ 22:51

LT 1750/-30 WT 1800/-40 CylT2 11.4/0.7 (once inst. on) but I believe

- 7) Open green knobs four 1/4 turns and note any pressure changes (P / Δ) I remember
LS 1550/+10 HS 1750/+30 LP 1200/+20 temps were
LT 1770/+20 WT 1800/+0 around 11
- 8) Close cylinder box lid earlier due to
- 9) Vnc into into AO2 (192.168.84.138) cold night

- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 20:21:21, Rack laptop time 20:21:22

- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)

PaWT 850/N/A PaSP 770/N/A PLi840 23.6/N/A TMan 20.2/+3.6

- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open 310
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.

PaCO₂ 304 PaO₂ 87 ⇒ later, at 22:51 they are 313/90

- 18) Click Initialize Cal Flow button

Adjusted HA3

- ✓ 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 95 FISP (to bypass) ~~88~~ ⇒ 94 / 91
- ✓ 20) Toggle changeover to check flows in other position
FIWT (to bypass) 90 FISP (to cell) 88 ⇒ 95 / 89
- ✓ 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- ✓ 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- ✓ 23) Close cylinder box lid
- ✓ 24) Return to WT selected when done checking regulators
- ✓ 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- ✓ 26) Light lamp and ensure that it comes on UTC = 20:48 (21:25 on)
- ✓ 27) If necessary, adjust PaO2 to keep signal below 9.5 V O2 signal = 8.1 20110628
- ✓ 28) Open manual Line Purge on/off valve
- ✓ 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- ✓ 30) Click Initialize Sample Flow button
- ✓ 31) Pump box Pump 1 breaker on
- ✗ 32) If necessary, adjust Line Purge regulator to 2 psig
- ✓ 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 795 SA Purge Flow 106.7
- ✓ 34) Snoop trap fittings
- ✓ 35) >= 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
20:58	NA	0.8	1.1	NA	NA	8.3	NA	0.02	5.8	4.6	5.6
21:13	533	0.79	1.79	10	-12	-3	21	0.03	5.5	4.2	4.8
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- ✓ 36) Enable changeover valve (uncheck disable) UTC = 20:59
- ✓ 37) >= 10 min. after change-over enable, record values in table above
- ✗ 38) Disable changeover
- ✗ 39) If necessary, toggle changeover to get SP to Cell
- ✗ 40) Click Close WT 248 valve

C. ~~40~~ min before take-off

- ✗ 1) WT 248 valve to Auto (uncheck close)
- ✗ 2) Enable changeover (uncheck disable) 3.0
- ✓ 3) Adjust / record program parameters (initially set to a, 15, ~~15~~, 3, 2)
Flag a Cal Interval 15 Cal Period 30 LTF 3 WTF 2
- ✓ 4) Click Start button on main screen UTC = 21:15:40
- ✓ 5) Note cryo temperature Cryo = -78.4
- ✓ 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WTFreq to 4
- ✓ 7) Immediately before runway, switch 3-way valve to inlet UTC = 23:08:
- ✓ 8) Note time of wheels up UTC = 23:09:30
- ✓ 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve 00:06

21:38
closed WT
disabled changeover
SP to cell

when 30 mins before
WT248 → open
enable changeover
adjust to 15/30/3/1

✓ T man WTFreq → 4 Calint → 50 @ 22:59

22:08 - set WT back to auto
Calint to 15
WTFreq to 1 ✓

22:34: takeoff further delayed
WT → closed changeover SP → cell
22:43: Now aiming for 11:00 takeoff,
so WT auto, chover on

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cal.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = ~~00:09:00~~ → 00:11:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = __ : __ : __
- 3) On final descent, open Line Purge cylinder green valve and on/off valve

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cal at same altitude on the way up and down above 29 kft, and avoiding any cal on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 06:28:50? 28:50
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 06:29:20
- 3) Note cryo temperature Cryo = -78
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

I. Preflight

- A. Day(s) before flight Date = 110629
- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
 - 2) Install trap in dewar Trap Letters Top/Bottom = A/C
 - 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 847 PaSP 761 PLi840 33.6 TMan 18.5 UTC = 00:34 on 110629
 - 4) Crack and close green valves, then record cylinder pressures
LS 1530 HS 1730 LP 1110 UTC = 00:36
 LT 1755 WT 1605 CylT2 11.0
 - 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
 - 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

- B. 2-hours before take-off Instrument Operator JDB
- 1) Rack power switch on
 - 2) O₂ box Power breaker on
 - 3) Laptop power on
 - 4) Pump box Power breaker on
 - 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 22:10
 - 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1525/+5 HS 1720/-20 LP 1130/+20
 LT 1760/+5 WT 1600/-5 CylT2 11 / 0 (once inst. on)
 - 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS 1530/+5 HS 1725/+5 LP 1140/+10
 LT 1760/0 WT 1600/0
 - 8) Close cylinder box lid
 - 9) Vnc into AO2 (192.168.84.138)
 - 10) Start AO2 program by clicking play in higold.vdp
 - 11) Ensure that no USB errors are present in boxes at bottom of screen
 - 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 22:21:47, Rack laptop time 22:21:48
 - 13) Cylinder box Power breaker on
 - 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 853/+6 PaSP 768/+7 PLi840 45.5/+11.9 TMan 19.8/+1.3
 - 15) Pump box Pump 2 breaker on
 - 16) Manual VAC valve open 305
 - 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 303 PaO₂ 88
 - 18) Click Initialize Cal Flow button

- ✓ 19) Ensure that flow starts through both lines (110 ± 10)
 FIWT (to cell) 89 FISP (to bypass) 83
- ✓ 20) Toggle changeover to check flows in other position
 FIWT (to bypass) 87 FISP (to cell) 86
- X 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- ✓ 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- ✓ 23) Close cylinder box lid
- ✓ 24) Return to WT selected when done checking regulators
- ✓ 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- ✓ 26) Light lamp and ensure that it comes on UTC = 22:29
- ✓ 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.89
- ✓ 28) Open manual Line Purge on/off valve
- ✓ 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- ✓ 30) Click Initialize Sample Flow button
- ✓ 31) Pump box Pump 1 breaker on
- X 32) If necessary, adjust Line Purge regulator to 2 psig
- ✓ 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
 PaSA 790 SA Purge Flow 10.8
- ✓ 34) Snoop trap fittings
- ✓ 35) >= 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>22:42</u>	NA	<u>1.0</u>	<u>1.0</u>	NA	NA	<u>5.2</u>	NA	<u>.03</u>	<u>5.4</u>	<u>4.9</u>	<u>5.2</u>
<u>22:56</u>	<u>544</u>	<u>0.77</u>	<u>1.8</u>	<u>7.4</u>	<u>-14</u>	<u>-5.9</u>	<u>21.6</u>	<u>0.03</u>	<u>5.7</u>	<u>5.5</u>	<u>4.2</u>
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- ✓ 36) Enable changeover valve (uncheck disable) UTC = 22:43
- ✓ 37) >= 10 min. after change-over enable, record values in table above
- ✓ 38) Disable changeover
- ✓ 39) If necessary, toggle changeover to get SP to Cell
- ✓ 40) Click Close WT 248 valve

45

C. ~~40~~-min before take-off

Cleared GMT Midnight
 23:59:59 w/o
 issue while on SA

- ✓ 1) WT 248 valve to Auto (uncheck close)
- ✓ 2) Enable changeover (uncheck disable) 3.0
- ✓ 3) Adjust / record program parameters (initially set to a, 15, ~~27~~, 3, 2)
 Flag a Cal Interval 15 Cal Period 3.0 LTF 3 WTF 2
- ✓ 4) Click Start button on main screen UTC = 23:13:30
- ✓ 5) Note cryo temperature Cryo = -78.3
- ✓ 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WTFreq to 4
- ✓ 7) Immediately before runway, switch 3-way valve to inlet UTC = 00:03:40
- ✓ 8) Note time of wheels up UTC = 00:04:53
- ✓ 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve 00:13:15

Callmt => 30
 to catch
 profile out of
 Cape Grim Obs

Some additional values, taken @ 23:58
 O₂V = 7.97 PaWT = 83 PaSP = 778 PaCO₂ = 311 PaO₂ = 89.9

✓ set cal into to 50 @ 0:17:00 (LS purging)

Date 110704 Campaign HIPPO4 Flight RFO8 From YPDN To PGSN
Darwin Saigon

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight Date = 110703

- ✓ 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- ✓ 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- ✓ 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures

PaWT 842 PaSP 760 PLi840 23.1 TMan 24.5 UTC = 1:00

- ✓ 4) Crack and close green valves, then record cylinder pressures
LS 1610 HS 1810 LP 1110 UTC = 1:03
LT 1860 WT 1510 CylT2 24.9

- ✓ 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)

- ✓ 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

EDIT

Add in 1-2 hrs of LP: Pump on, Enable Pump Box, SA Purge, Instrument Operator JDB

B. 2-hours before take-off

- ✓ 1) Rack power switch on
- ✓ 2) O₂ box Power breaker on
- ✓ 3) Laptop power on
- ✓ 4) Pump box Power breaker on
- ✓ 5) Load dry-ice in dewar to within 0.5 inches of lid

UTC = 23:00

- ✓ 6) Record hi-side cylinder pressures and changes overnight (P / Δ)

LS 1600 / -10 HS 1795 / -15 LP 1060 / -50

LT 1855 / -5 WT 1495 / -15 CylT2 22.4 / -2.5 (once inst. on)

- ✓ 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)

LS 1605 / +5 HS 1800 / +5 LP 1100 / +40

LT 1855 / 0 WT 1505 / +10

- ✓ 8) Close cylinder box lid

- ✓ 9) Vnc into into AO2 (192.168.84.138)

- ✓ 10) Start AO2 program by clicking play in higold.vdp

- ✓ 11) Ensure that no USB errors are present in boxes at bottom of screen

- ✓ 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 23:12:02, Rack laptop time 23:12:03

- ✓ 13) Cylinder box Power breaker on

- ✓ 14) Record instrument pressures and changes overnight (P / Δ)

PaWT 847 / +5 PaSP 763 / -3 PLi840 26.6 / TMan 24.8 / +0.3

- ✓ 15) Pump box Pump 2 breaker on

- ✓ 16) Manual VAC valve open

- ✓ 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.

PaCO₂ 313 PaO₂ 89

- ✓ 18) Click Initialize Cal Flow button

Set Purge Val
to 2.1 V,
Set flow,
Watch
SA purge = 100
Start UTC
1:20

- ✓ 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 103 FISP (to bypass) 95
- ✓ 20) Toggle changeover to check flows in other position
FIWT (to bypass) 102 FISP (to cell) 96
- ✗ 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ± 2 scfm
- ✓ 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 \pm 5 torr
- ✓ 23) Close cylinder box lid
- ✓ 24) Return to WT selected when done checking regulators
- ✓ 25) Check that PdWT (± 0.1), PdSP (± 0.1), and PdO2 (± 0.01) are controlling
- ✓ 26) Light lamp and ensure that it comes on UTC = 23:24
- ✗ 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 6.7, rising
- ✓ 28) Open manual Line Purge on/off valve 7.1 @ 0:29
- ✓ 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- ✓ 30) Click Initialize Sample Flow button
- ✓ 31) Pump box Pump 1 breaker on
- ✓ 32) If necessary, adjust Line Purge regulator to 2 psig (first time I have)
- ✓ 33) Ensure that PaSA stabilizes near 795 (± 10) torr after 2 min. needed to
PaSA 790 SA Purge Flow 107
- ✓ 34) Snoop trap fittings
- ✓ 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	m Δ	PdO2n	PdSPn	PdWTn	PaSAn
<u>23:48</u>	NA	<u>0.89</u>	<u>0.92</u>	NA	NA	<u>0.77</u>	NA	<u>0.03</u>	<u>5.1</u>	<u>4.31</u>	<u>3.14</u>
<u>23:59</u>	<u>570</u>	<u>0.67</u>	<u>1.59</u>	<u>15.3</u>	<u>14</u>	<u>-0.38</u>	<u>29</u>	<u>0.03</u>	<u>4.6</u>	<u>4.03</u>	<u>5.22</u>
nominal	500+	0.7	2.0	± 10	± 10	± 10	± 20	0.05	5.0	5.0	5.0

- ✓ 36) Enable changeover valve (uncheck disable) UTC = 11:49
- ✓ 37) ≥ 10 min. after change-over enable, record values in table above
- ✓ 38) Disable changeover
- ✓ 39) If necessary, toggle changeover to get SP to Cell
- ✓ 40) Click Close WT 248 valve

C. ⁴⁵~~40~~-min before take-off

- ✓ 1) WT 248 valve to Auto (uncheck close)
- ✓ 2) Enable changeover (uncheck disable) 3.0
- ✓ 3) Adjust / record program parameters (initially set to a, 15, ~~22.5~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 Ltf 3 Wtf 2
- ✓ 4) Click Start button on main screen UTC = 0:44:18
- ✓ 5) Note cryo temperature Cryo = -78.6
- ✓ 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4 01:22
- ✓ 7) Immediately before runway, switch 3-way valve to inlet UTC = 01:43:30
- ✓ 8) Note time of wheels up UTC = 01:44:12
- ✓ 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

Inlet Purge valves
closed 01:48:45

Door close 01:24:30

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 02:25:00 - 27:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 07:03:00 - 04:00
- 3) On final descent, open Line Purge cylinder green valve and on/off valve 07:04:31

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 07:42:54
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 074330
- 3) Note cryo temperature Cryo = -78.3
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

I. Preflight

A. Day(s) before flight Date = 110705

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures

Added a small amt. of dry ice to dewar that Pavel had leftover from OMS

PaWT 838 PaSP 770 PLi840 25.4 TMan 22.7 UTC = 0:35
 4) Crack and close green valves, then record cylinder pressures
 LS 1560 HS 1770 LP 1060 UTC = 0:45
 LT 1810 WT 1300 CylT2 20.8

5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)

6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

7) *Enable Pump + Cyl boxes by clicking BoxT/enable & Boxenable*
 Instrument Operator JDB to LP. *10X each. Open LP green + on/off. Ensure 3-way*

B. 2-hours before take-off

Turn Pump Box on (cond. cyl)

- 1) Rack power switch on *0:40*
- 2) O₂ box Power breaker on *close LP / on/off*
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 00:35

Click init. sample flow. Check that SA Purge => 110

6) Record hi-side cylinder pressures and changes overnight (P / Δ)
 LS 1520 / -40 HS 1510 / +40 LP 990 / -10
 LT 1895 / +85 WT 1340 / +40 CylT2 27.7 / +5 (once inst. on)

7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
 LS 1520 / 0 HS 1510 / 0 LP 1080 / +90
 LT 1895 / 0 WT 1340 / 0

- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 00:44:19, Rack laptop time 00:44:22

13) Cylinder box Power breaker on

14) Record instrument pressures and changes overnight (P / Δ)
 PaWT 862 / +24 PaSP 790 / -20 PLi840 30.2 / +5 TMan +63 / 29

- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
 PaCO₂ 319 PaO₂ 87
- 18) Click Initialize Cal Flow button

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 111 FISP (to bypass) 102
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 111 FISP (to cell) 104
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on
UTC = 00:54
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V
O₂ signal = 8.94 PaO₂ ⇒ 81
- 28) Open manual Line Purge on/off valve
Adjusted PaO₂ down
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
to increase signal
- 30) Click Initialize Sample Flow button
from 6.4 → 8.9
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 710 SA Purge Flow 107
- 34) Snoop trap fittings
- 35) >= 10 min. after lamp on record values in first row of table below

between, plane taxied and P went up and down, causing sigs of noise ↑

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
01:09	NA	0.77	0.77	NA	NA	6.4	NA	0.026	4.3	4.4	5.8
01:27	689	0.64	1.7	15.6	-11.9	2.2	27	0.02	5.7	4.5	4.8
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 01:10
- 37) >= 10 min. after change-over enable, record values in table above
- 38) Disable changeover
- 39) If necessary, toggle changeover to get SP to Cell
- 40) Click Close WT 248 valve

C. ⁴⁵ ~~40~~ min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) 310
- 3) Adjust / record program parameters (initially set to a, 15, ~~278~~, 3, 2)
Flag a Cal Interval 15 Cal Period 30 Ltf 3 Wtf 2
- 4) Click Start button on main screen UTC = 01:32:15
- 5) Note cryo temperature Cryo = -78.8
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 02:25:30
- 8) Note time of wheels up UTC = 02:26:15
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve 02:28:40

EDIT: Set alarm to remind

Date 110706 Campaign HIPPO4 Flight RF09

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

FORGET
AGAIN

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 03:06:00 - 08:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = : :
- 3) On final descent, open Line Purge cylinder green valve and on/off valve ~ 08:11

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

08:46:30 cals → auto

- 1) Note time of wheels down UTC = 08:50:09
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 05110
- 3) Note cryo temperature Cryo = -78.7
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Edit: 24) check that all boxes on check sheet are checked/checked.

Replace A02 filter

- Pull vacuum w/ sa 248 closed and SA selected and SP28 open
- Check PaSA before/after to verify leak
- Replace w/ 1µm cellulose nitrate

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight Date = 110709

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = ___ / ___
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures
PaWT 797 PaSP 794 PLi840 39 TMan 28 UTC = 23 : 40
- 4) Crack and close green valves, then record cylinder pressures
LS 1500 HS 1690 LP 940 UTC = 23 : 40
LT 1770 WT 860 CylT2 173
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off Instrument Operator _____

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = ___ : ___
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS ___ / ___ HS ___ / ___ LP ___ / ___
LT ___ / ___ WT ___ / ___ CylT2 ___ / ___ (once inst. on)
- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)
LS ___ / ___ HS ___ / ___ LP ___ / ___
LT ___ / ___ WT ___ / ___
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time ___ : ___ : ___ , Rack laptop time ___ : ___ : ___
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT ___ / ___ PaSP ___ / ___ PLi840 ___ / ___ TMan ___ / ___
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open 308 ?!
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ ___ PaO₂ ___
- 18) Click Initialize Cal Flow button

Date 110709 Campaign HIPPO4 Flight REF ^{Maint Def}

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 102 FISP (to bypass) 96
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 102 FISP (to cell) 97
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = : :
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal =
- 28) Open manual Line Purge on/off valve
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA SA Purge Flow
- 34) Snoop trap fittings
- 35) >= 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>23 :04</u>	NA	<u>0.77</u>	<u>0.8</u>	NA	NA	<u>2.2</u>	NA	<u>.02</u>	<u>5.0</u>	<u>5.1</u>	<u>2.9</u>
<u>23 :24</u>	613	<u>0.63</u>	<u>1.7</u>	<u>10.3</u>	<u>-9.4</u>	<u>-0.02</u>	<u>20</u>	<u>0.02</u>	<u>5.7</u>	<u>5.0</u>	<u>5.1</u>
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 23 : 11
 - 37) >= 10 min. after change-over enable, record values in table above
 - 38) Disable changeover
 - 39) If necessary, toggle changeover to get SP to Cell
 - 40) Click Close WT 248 valve
- C. ⁴⁵~~40~~-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable) ^{3.0}
- 3) Adjust / record program parameters (initially set to a, 15, ~~215~~, 3, 2)
Flag Cal Interval Cal Period LTf WTf
- 4) Click Start button on main screen UTC = : :
- 5) Note cryo temperature Cryo =
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WTfreq to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = : :
- 8) Note time of wheels up UTC = : :
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight

Date = 110706

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures

PaWT 889 PaSP 828 PLi840 24.7 TMan 32.4 UTC = 23:29

- 4) Crack and close green valves, then record cylinder pressures

LS 1530 HS 1750 LP 1000 UTC = 23:3

LT 1810 WT 1110 CylT2 21.1

- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)

- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack,

- 7) Enable PB, CB; init. sample 23:45 - 00:27

B. 2-hours before take-off

Instrument Operator JDB

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 13:50
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)

LS 1590/+60 HS 1810/-60 LP 960/-40
LT 1890/+80 WT 1120/+10 CylT2 29.3/+8.2 (once inst. on)

- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ)

LS 1590/0 HS 1810/0 LP 980/+20
LT 1890/0 WT 1130/+10

- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times

AO2 PC Time 14:07:15, Rack laptop time 14:07:16

- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)

PaWT 867/-22 PaSP 7987+30 PLi840 27/+2.3 TMan 26.4-6

- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
- 18) Click Initialize Cal Flow button

PaCO₂ 321 PaO₂ 81

7/9/2011
VB started:
Method n of subject is finalized

only wt

(short on time this morning)

- 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 107 FISP (to bypass) 101
- 20) Toggle changeover to check flows in other position
FIWT (to bypass) 108 FISP (to cell) 102
- 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ± 2 sccm
- 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 \pm 5 torr
- 23) Close cylinder box lid
- 24) Return to WT selected when done checking regulators
- 25) Check that PdWT (± 0.1), PdSP (± 0.1), and PdO2 (± 0.01) are controlling
- 26) Light lamp and ensure that it comes on UTC = 02:15
- 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 8.40
- 28) Open manual Line Purge on/off valve \Rightarrow 8.89 @
- 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- 30) Click Initialize Sample Flow button
- 31) Pump box Pump 1 breaker on
- 32) If necessary, adjust Line Purge regulator to 2 psig
- 33) Ensure that PaSA stabilizes near 795 (± 10) torr after 2 min.
PaSA 792 SA Purge Flow 100.2
- 34) Snoop trap fittings
- 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>14:26</u>	NA	<u>0.7</u>	<u>1.4</u>	NA	NA	<u>7.6</u>	NA	<u>0.03</u>	<u>6</u>	<u>4.4</u>	<u>3.1</u>
<u>14:37</u>	<u>650</u>	<u>0.7</u>	<u>1.5</u>	<u>17</u>	<u>-8.8</u>	<u>9.8</u>	<u>26</u>	<u>0.03</u>	<u>5.1</u>	<u>5.1</u>	<u>5.0</u>
nominal	500+	0.7	2.0	± 10	± 10	± 10	± 20	0.05	5.0	5.0	5.0

- 36) Enable changeover valve (uncheck disable) UTC = 14:27
 - 37) ≥ 10 min. after change-over enable, record values in table above
 - 38) Disable changeover
 - 39) If necessary, toggle changeover to get SP to Cell
 - 40) Click Close WT 248 valve
- C. ⁴⁵~~40~~-min before take-off

- 1) WT 248 valve to Auto (uncheck close)
- 2) Enable changeover (uncheck disable)
- 3) Adjust / record program parameters (initially set to a, 15, ~~210~~, 3, 2)
Flag a Cal Interval 15 Cal Period 30 LTF 3 Wtf 2
- 4) Click Start button on main screen UTC = 14:50:40
- 5) Note cryo temperature Cryo = -78.8
- 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4
- 7) Immediately before runway, switch 3-way valve to inlet UTC = 15:31:26
- 8) Note time of wheels up UTC = 15:33:52
- 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

15:38:10

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust calcs.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- could
system
shot
down*
- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 16:04:30 - 06:30
 - 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) =
 - 3) On final descent, open Line Purge cylinder green valve and on/off valve

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping calcs at same altitude on the way up and down above 29 kft, and avoiding any calcs on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 21:48:30
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge 214922
- 3) Note cryo temperature Cryo = -79.2
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Does $P_{idWT} \rightarrow +5$ when main vac is closed
and WT248 is open postflight.

Date 110710 Campaign WIPP04 Flight RE11 From PANC To PANC

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight

Date = 110709

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = /
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures 797 794 39
PaWT ~~82~~ PaSP ~~726~~ PLi840 ~~256~~ TMan 28 UTC = 23:40
- 4) Crack and close green valves, then record cylinder pressures
LS 1500 HS 1690 LP 940 UTC = 23:40
LT 1770 WT 860 CylT2 17.3
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off

Instrument Operator JDB

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 16:20
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1480/-20 HS 1520/-170 LP 810/-130 ~~WT 860~~
LT 1270/-500 WT 180/-680 CylT2 18.3/-1 (once inst. on) ~~17.3~~
- 7) Open green knobs four ¼ turns and note any pressure changes (P / Δ) No alarm necessary - we had to shut system down in a rush at the end of maint day while system was mid-cal,
LS 1490/+10 HS 1700/+180 LP 910/-30
LT 1780/+810 WT 810/+630
- 8) Close cylinder box lid
- 9) Vnc into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 16:39:01, Rack laptop time 16:39:05
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ)
PaWT 835/+38 PaSP 777/-15 PLi840 228/-55 TMan 19.6-8.4
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 304 PaO₂ 86 (new lower settings from maint day (see separate check sheet and AO2 book))
- 18) Click Initialize Cal Flow button

JDB

Date 110710 Campaign HIPPOY Flight RF11

- ✓ 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 91 FISP (to bypass) 87
- ✓ 20) Toggle changeover to check flows in other position
FIWT (to bypass) 90 FISP (to cell) 89
- ✓ 21) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- ✓ 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- ✓ 23) Close cylinder box lid
- ✓ 24) Return to WT selected when done checking regulators
- ✓ 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- ✓ 26) Light lamp and ensure that it comes on UTC = 16:41
- ✓ 27) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.66
- ✓ 28) Open manual Line Purge on/off valve
- ✓ 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- ✓ 30) Click Initialize Sample Flow button
- ✓ 31) Pump box Pump 1 breaker on
- ✓ 32) If necessary, adjust Line Purge regulator to 2 psig
- ✓ 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 710 SA Purge Flow 107
- ✓ 34) Snoop trap fittings
- ✓ 35) >= 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
<u>16:52</u>	NA	<u>0.74</u>	<u>1.4</u>	NA	NA	<u>17.1</u>	NA	<u>0.02</u>	<u>5.28</u>	<u>4.88</u>	<u>4.62</u>
<u>17:03</u>	<u>573</u>	<u>0.89</u>	<u>2.1</u>	<u>17.9</u>	<u>-2.2</u>	<u>7.8</u>	<u>20.4</u>	<u>0.02</u>	<u>5.16</u>	<u>4.56</u>	<u>4.82</u>
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- ✓ 36) Enable changeover valve (uncheck disable) UTC = 16:52
- ✓ 37) >= 10 min. after change-over enable, record values in table above
- ✓ 38) Disable changeover
- ✓ 39) If necessary, toggle changeover to get SP to Cell
- ✓ 40) Click Close WT 248 valve

C. ⁴⁵~~40~~-min before take-off

- ✓ 1) WT 248 valve to Auto (uncheck close)
- ✓ 2) Enable changeover (uncheck disable) 3.0
- ✓ 3) Adjust / record program parameters (initially set to a, 15, ~~20~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 LTF 3 Wtf 2
- ✓ 4) Click Start button on main screen UTC = 17:17:13
- ✓ 5) Note cryo temperature Cryo = -78.6
- ✓ 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and Wtfreq to 4
- ✓ 7) Immediately before runway, switch 3-way valve to inlet UTC = 18:05:35
- ✓ 8) Note time of wheels up UTC = 18:06:41
- ✓ 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve

⊙ 18:51:30

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cals.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

well, this time I wrote a note to myself and set an alarm. The note was 2 hours too early; the alarm went off literally at the exact moment that Steve announced our final descent.

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 18:49:00 - 51:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = : :
- 3) On final descent, open Line Purge cylinder green valve and on/off valve 02:14:30

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cals at same altitude on the way up and down above 29 kft, and avoiding any cals on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

III. Postflight

- 1) Note time of wheels down UTC = 02:23:36
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature Cryo = -78.8
- 4) Click Stop button 02:24:21
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcyllg.txt, and AO2*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

NCAR Airborne Oxygen Instrument (AO2) Checklist V. 2011.06.12

I. Preflight

A. Day(s) before flight Date = 110711

- 1) Prepare trap with clean glass beads filled to 1 inch from bottom
- 2) Install trap in dewar Trap Letters Top/Bottom = B / D
- 3) Power rack, O₂ box, Cylinder box, laptop, vnc, start program, and record pressures *Couldn't get; not enough time - no maint. day*
PaWT PaSP PLi840 TMan UTC = :
- 4) Crack and close green valves, then record cylinder pressures
LS 1430 HS 1600 LP 900 UTC = 03:40
LT 1730 WT 620 CylT2 19
- 5) Log each hi-side cylinder pressure in software (pressures must be logged at least once between flights)
- 6) Stop program, close Visual Basic and vnc, shut down Windows, power down O₂ and Cylinder box, power down laptop and rack

B. 2-hours before take-off Instrument Operator JDB

- 1) Rack power switch on
- 2) O₂ box Power breaker on
- 3) Laptop power on
- 4) Pump box Power breaker on
- 5) Load dry-ice in dewar to within 0.5 inches of lid UTC = 16:10
- 6) Record hi-side cylinder pressures and changes overnight (P / Δ)
LS 1430 / 0 HS 1560 / -40 LP 880 / -20
LT 1730 / +10 WT 600 / -20 CylT2 15.1 / -3.9 (once inst. on)
- 7) Open green knobs four 1/4 turns and note any pressure changes (P / Δ)
LS 1440 / +10 HS 1640 / +80 LP 900 / +20
LT 1740 / +10 WT 620 / +20
- 8) Close cylinder box lid
- 9) Vnc into into AO2 (192.168.84.138)
- 10) Start AO2 program by clicking play in higold.vdp
- 11) Ensure that no USB errors are present in boxes at bottom of screen
- 12) Check that NTP time sync is working on AO2 and laptop, >5-min after first sync, record times
AO2 PC Time 0:37:39, Rack laptop time 6:37:41
- 13) Cylinder box Power breaker on
- 14) Record instrument pressures and changes overnight (P / Δ) 816/786/18/224
PaWT 851 / X PaSP 776 / X PLi840 12 / X TMan 19.4 / X
- 15) Pump box Pump 2 breaker on
- 16) Manual VAC valve open
- 17) Check that PaCO₂ = 325 torr (± 5) and PaO₂ = 90 torr (± 1). If not, adjust.
PaCO₂ 304 PaO₂ 86 305/85
- 18) Click Initialize Cal Flow button

LOG
CYLINDER
VALS
Get wrenches for cabin CO₂ test out + ready

~~1730~~
~~1430~~

Date 110711 Campaign HIPPO4 Flight PF12 ~~PF1~~

- ✓✓ 19) Ensure that flow starts through both lines (110 ± 10)
FIWT (to cell) 91 FISP (to bypass) 88 94/92
- ✓✓ 20) Toggle changeover to check flows in other position
FIWT (to bypass) 90 FISP (to cell) 90 93/91
- ✗ ~~21~~) If necessary, adjust HA-3 to match FIWT on bypass and cell to ±2 sccm
- ✓✓ 22) Check / adjust regulator pressures for all 4 gases to PaSP of 785 +/- 5 torr
- ✓✓ 23) Close cylinder box lid
- ✓✓ 24) Return to WT selected when done checking regulators
- ✓✓ 25) Check that PdWT (±0.1), PdSP (±0.1), and PdO2 (±0.01) are controlling
- ✓✓ 26) Light lamp and ensure that it comes on UTC = 16:48 17:32
- ✗ ~~27~~) If necessary, adjust PaO2 to keep signal below 9.5 V O₂ signal = 7.62
- ✗ ~~28~~) Open manual Line Purge on/off valve
- ✓✓ 29) Ensure inlet manual 3-way valve to Line Purge cylinder
- ✓✓ 30) Click Initialize Sample Flow button
- ✓✓ 31) Pump box Pump 1 breaker on
- ✗ ~~32~~) If necessary, adjust Line Purge regulator to 2 psig
- ✓✓ 33) Ensure that PaSA stabilizes near 795 (±10) torr after 2 min.
PaSA 715 SA Purge Flow 105
- ✗ ~~34~~) Snoop trap fittings
- ✗ ✓ 35) ≥ 10 min. after lamp on record values in first row of table below

UTC	O2d	CO2n	O2n	SPm	WTm	Totm	mΔ	PdO2n	PdSPn	PdWTn	PaSAn
16:55	NA	0.88	1.3	NA	NA	11.9	NA	0.026	4.4	5.1	3.4
17:06	563	0.91	1.5	12	-1.6	4.7	14	0.024	4.1	4.1	4.1
nominal	500+	0.7	2.0	±10	±10	±10	±20	0.05	5.0	5.0	5.0

- ✗ ✓ 36) Enable changeover valve (uncheck disable) UTC = 16:56
- ✗ ✓ 37) ≥ 10 min. after change-over enable, record values in table above
- ✗ ~~38~~) Disable changeover
- ✓✓ 39) If necessary, toggle changeover to get SP to Cell
- ✗ ✓ 40) Click Close WT 248 valve

C. ⁴⁵~~40~~-min before take-off

OH, HENRY! @ 17:15, Henry accidentally shut off power. Going back through checklist.

- ✗ ✓ 1) WT 248 valve to Auto (uncheck close)
- ✓ 2) Enable changeover (uncheck disable) 3.0
- ✓ 3) Adjust / record program parameters (initially set to a, 15, ~~28~~, 3, 2)
Flag a Cal Interval 15 Cal Period 3.0 Ltf 3 Wtf 2
- ✓ 4) Click Start button on main screen UTC = 17:36:30
- ✓ 5) Note cryo temperature Cryo = -78
- ✓ 6) After 3rd Cal cycle (37.5 min after clicking start, sequence: WT-HS-LS-LT-SA-LS-HS-SA-HS-LS-WT) set Cal Interval to 50 and WTfreq to 4 18:16:00
- ✓ 7) Immediately before runway, switch 3-way valve to inlet UTC = 18:23:55
- ✓ 8) Note time of wheels up UTC = 18:24:22
- ✓ 9) Close Inlet Purge cylinder green valve and manual Inlet Purge on/off valve 18:29:50

— Announce water on CO₂ cabin values

Date 11/07/11 Campaign HIPPO4 Flight RF12

II. During Flight

Keep VNC off as much as possible, only connecting when necessary to adjust cal.

Record flight notes in text file AO2_YYYYMMDD_RF##_Notes.txt and add any action items to AO2_TODO_YYMMDD_GV.doc

- 1) At high point of first ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = 19:08:00 - 19:10:00
- 2) At high point of last ascent, while sampling air, conduct 30-second breath test on inlet fittings UTC (start) = : :
- 3) On final descent, open Line Purge cylinder green valve and on/off valve 0:27:15

Adjust cal schedule as necessary with a goal of sampling at least some portion of every level low and high leg, avoiding overlapping cal at same altitude on the way up and down above 29 kft, and avoiding any cal on northernmost and southernmost profile (keeping in mind 45 second inlet delay):

193605 - manually forced cal

III. Postflight

- 1) Note time of wheels down UTC = 00:55:50 **DONE!**
- 2) As soon as off runway, request permission and switch inlet 3-way to line purge
- 3) Note cryo temperature Cryo = -80.5 → 56:48
- 4) Click Stop button
- 5) Close manual VAC valve
- 6) **Close all 4 cal cylinder green valves**
- 7) Close cylinder box lid
- 8) Wait 5 to 10 minutes after touchdown
- 9) **Close Line Purge cylinder green valve** and manual Line Purge on/off valve
- 10) Cylinder box Power breaker off
- 11) Pump box Pump 2 breaker off
- 12) Pump box Pump 1 breaker off
- 13) Pump box Power breaker off
- 14) Close program and Visual Basic
- 15) Copy data (*.mr, *.hr, *.txt) to laptop and then data and notes, etc. to pen drive
- 16) Shut down AO2 PC
- 17) Shut down laptop
- 18) After green "SP to Cell" light has gone out, O₂ box Power breaker off
- 19) Rack power switch off
- 20) Pull trap, jumper quick-connects, and install stopper
- 21) Open trap and remove glass beads
- 22) ftp *.mr, *.hr, hgcylllog.txt, and AO2_*_Notes.txt files for this flight to the ao2raw directory on catalog.eol.ucar.edu (or email if ftp does not work)
- 23) email a scan of this checksheet to BBS (or fax if scanner not available)

Cabin P test

Manual cal → 10 mins one P
10 mins charging
10 mins back ?

53:00 → LP
19:53:20 → open cabin
20:18 Panel leaves chair → front of plane
20:26 back to sample.
line closed @ T.

Cabin CO₂ test

Get wrenches out

- 1) close LP
- 2) Unscrew 1/8" plug on tee near LP valve
- 3) Switch 3-way to LP

Ask ppl not to get too close to inlet

- 4) "Sample" whole way down/up to see variable effect.

22 29 44 - @ 43kft, back to cabin air sucking into system,
22 38 ~ cal
22 46 ~ back to sampling cabin
22 49:55 - back to SAMPLE

PCAB Test

21:46 - forced purge → cal. Purging
21:50 - Manual control, purge off. LS purging
21:58 - charging P down (cabin) from 640 → 620
22:04 - charging P back up from 620 → 640
22:18 - back to cal cycle