

T-28 Pilot Report

Flight: 748
Date: 05/26/2000
Flight Time: 21:49:00 – 22:54:30
Pilot: Tom Root
Controller: Andy Detwiler
Location: Goodland, KS
Mission: Research flight

Computer Time	Video Time	Comments
	21:59:10	Take off
	22:01:40	FM and Cloud Switch Test
	22:02:45	FM and Cloud Switch off
	22:12:30	Turn left 20° to heading 190°
	22:13:45	In cloud
	22:14:08	At flight level 19,000 feet
	22:15:22	Light turbulence occasionally moderate. Also some ice on canopy. Precipitation visible on video.
	22:16:13	Light rime icing
	22:17:05	Continuous light precipitation
	22:17:35	Turning 5° left.
	22:17:57	Light precipitation and some lightning
	22:18:45	Low voltage indication and primary attitude indicator failure
	22:20:00	GPS inoperative
	22:22:36	Oder in cabin. Moderate icing. Pilot reports possible lightning strike
	22:33:30	Video goes out
	22:38:08	Audio goes out

NOTES

Weather

Maintenance

Operations